

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Building Information

Building Information**1. Name of School District:**

SCHENECTADY CITY SD

2. SED District 8-Digit BEDS Code:

530600010000

3. Building Name:

Pleasant Valley

4. SED 4-Digit Facility Code:

0019

5. Survey Inspection Date:

11/06/2015

6. Building 911 Address:

1097 Forest Road

7. City:

Schenectady

8. Zip Code:

12303

9. Certificate of Occupancy Status:

- ☒ A - Annual
☐ T - Temporary
☐ N - None

10. Certificate of Occupancy Expiration Date:

08/01/2016

Building Age, Gross Square Footage and Maintenance Staff**11. Year of Original Building:**

1919

12. Gross square ft. of Building as currently configured:

57,740

13. Number of Floors:

3

14. How many full-time and part-time custodians are employed at the school (or work in the building)?

	Count Employees
Full-time custodians:	3
Part-time custodians:	0

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Building Information

	Count Employees
Totals:	3

Building Ownership and Occupancy Status

15. Building Ownership (check one):

- ☒ Owned and used by district
- ☐ Owned by District and leased to non-district entity
- ☐ Owned by District, part used by district, part leased to non-district entity
- ☐ Owned by non-district entity and leased to district

16. For which of the following purposes is the building currently used? (check all that apply)

- ☒ Used for student instructional purposes
- ☐ Used for district administration
- ☐ Used for other district purposes
- ☐ Used by other organization(s)

Building Users

17. How many students were registered to receive instruction in this building as of October 1, 2014? (If none, enter "0") and skip to "Program Spaces" section. (Do not include evening class students)

508

18. Of these registered students, how many receive most of their instruction in:

	Quantity
18a. Permanent instructional spaces (i.e., regular classrooms)	428
18b. Temporary instructional spaces (i.e., portable or demountable classrooms) attached to the building	0
18c. Non-instructional spaces used as instructional spaces	80

18c.1 If the answer is greater than zero, which types of non-instructional spaces were being used for instructional purposes on October 1, 2014? (check all that apply)

- ☒ Cafeteria
- ☐ Gymnasium
- ☒ Administrative Spaces
- ☒ Library
- ☒ Lobby
- ☐ Stairwell
- ☐ Storage space
- ☐ Other (please describe)
- ☐ None

19. Grades Housed:

K-6

20. For how many instructional days during the 2013-14 school year (July 1 through June 30, was the building closed due to facilities failures, system malfunctions, structural problems, fire, etc? (if none, enter "0")

0

21. Is the building used for instructional purposes in the summer?

- ☐ Yes
- ☒ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Building Information

22. Have there been renovations or construction in the building during the past 12 months?

☒ Yes

☐ No

23. Was major construction/renovation work since 2010 conducted when school was in session?

☐ Yes

☒ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Program Spaces

Program Spaces**24. Number of instructional classrooms:**

29

25. Gross square footage of all instructional classrooms (combined):

17,363.00

26. Other spaces provided: (check all that apply)

- | | | |
|---|---|--|
| <input type="checkbox"/> a. N/A (none) | <input checked="" type="checkbox"/> j. Health Office | <input checked="" type="checkbox"/> s. Resource Rooms |
| <input checked="" type="checkbox"/> b. Administration | <input type="checkbox"/> k. Home & Careers | <input type="checkbox"/> t. Science Labs |
| <input checked="" type="checkbox"/> c. Art | <input type="checkbox"/> l. Kitchen | <input checked="" type="checkbox"/> u. Special Education |
| <input type="checkbox"/> d. Audio Visual | <input type="checkbox"/> m. Large Group Instruction | <input type="checkbox"/> v. Swimming Pool |
| <input type="checkbox"/> e. Auditorium | <input checked="" type="checkbox"/> n. Library | <input checked="" type="checkbox"/> w. Teacher Resource |
| <input checked="" type="checkbox"/> f. Cafeteria | <input type="checkbox"/> o. Multipurpose Rooms | <input type="checkbox"/> x. Technology/Shop |
| <input type="checkbox"/> g. Computer Room | <input checked="" type="checkbox"/> p. Music | <input type="checkbox"/> y. Other (please describe) |
| <input checked="" type="checkbox"/> h. Guidance | <input type="checkbox"/> q. Pre-K | |
| <input checked="" type="checkbox"/> i. Gymnasium | <input checked="" type="checkbox"/> r. Remedial Rooms | |

26y. Describe other spaces

(No Response)

Space Adequacy**27. Rating of space adequacy:**

- ☒ Good
☐ Fair
☐ Poor

27a. Enter comments:

(No Response)

28. Estimated capital construction expenses anticipated for this building through 2020-2021 school year excluding maintenance (to be answered after the building inspection is complete) \$

4,586,500.00

29. Overall building rating (to be answered after the building inspection is complete)

- ☐ Excellent
☐ Satisfactory
☒ Unsatisfactory
☐ Poor

30. Was overall building rating established after consultation with health and safety committee?

- ☐ Yes
☒ No

A/E Information:**31. A/E Firm Name:**

Mosaic Associates Architects

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Program Spaces

32. A/E Firm Address:

The Frear Building
2 Third Street, Suite 440
Troy, NY 12180

33. A/E Firm Phone Number:

5184794000

34. E-mail:

mfanning@mosaicaa.com

35. A/E Name:

Michael Fanning, AIA

36. A/E License #:

018194

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Site Utilities

Site Utilities**37. Water**☒ Yes☐ No**37a. Type of Service:**☒ Municipal or Utility provided☐ Well☐ Other**37b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**37c. Year of Last Major Reconstruction/Replacement:**

1922

37d. Expected Remaining Useful Life (Years):

5

37e. Cost to Reconstruct/Replace \$:

21,000.00

37f. Comments:

Install a backflow preventor

38. Site Sanitary (H)☒ Yes☐ No**38a. Type of Service:**☒ Municipal or utility sewer☐ Site septic☐ Other**38b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**38c. Year of Last Major Reconstruction/Replacement:**

1922

38d. Expected Remaining Useful Life (Years):

5

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Site Utilities

38e. Cost to reconstruct/Replace \$:

115,000.00

38f. Comments:

Service is original to building, however no leaks or backups reported

39. Site Gas (H)

- ☒ Yes
☐ No

39a. Type of gas service:

- ☒ Natural Gas
☐ Liquid Petroleum

39b. Condition:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

39c. Year of Last Major Reconstruction/Replacement;

2015

39d. Expected Remaining Useful Life (Years):

11

39e. Cost to Reconstruct/Replace \$:

(No Response)

39f. Comments:

(No Response)

40. Site Fuel Oil (H)

- ☐ Yes
☒ No

41. Site Electrical, Including Exterior Distribution (H)

- ☒ Yes
☐ No

41a. Service Provider:

- ☒ Municipal or utility provided
☐ Self-Generated
☐ Other
☐ N/A

41b. Type of Service:

- ☐ Above Ground
☒ Below Ground
☐ N/A

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Site Utilities

41c. Condition:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

41d. Year of Last Major Reconstruction/Replacement:

1990

41e. Expected Remaining Useful Life (Years):

5

41f. Cost to Reconstruct/Replace \$:

49,000.00

41g. Comments:

Replace exterior fixtures mounted on the building

Stormwater Management**42. Closed Drainage Pipe Stormwater Management System****42a. Does this facility have a closed pipe system?**

- ☒ Yes
- ☐ No

42b. Condition:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

42c. Year of Last Major Reconstruction/Replacement:

2011

42d. Expected Remaining Useful Life (Years):

15

42e. Cost to Reconstruct/Replace \$:

(No Response)

42f. Comments:

(No Response)

43. Open Drainage Pipe Stormwater Management System**43a. Does this facility have an open stormwater system (ditch)?**

- ☐ Yes
- ☒ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Site Utilities

44. Catch Basins/Drop Inlets/Manholes**44a. Does this facility have catch basins/drop inlets/manholes?**

- ☒ Yes
☐ No

44b. Condition:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

44c. Year of Last Major Reconstruction/Replacement:

2011

44d. Expected Remaining Useful Life (Years):

15

44e. Cost to Reconstruct/Replace \$:

(No Response)

44f. Comments:

(No Response)

45. Culverts**45a. Does this facility have culverts?**

- ☐ Yes
☒ No

46. Outfalls**46a. Does this facility have outfalls?**

- ☐ Yes
☒ No

47. Infiltration Basins/Chambers**47a. Does this facility have infiltration basins/chambers?**

- ☐ Yes
☒ No

48. Retention Basins**48a. Does this facility have retention basins?**

- ☐ Yes
☒ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Site Utilities

49. Wetponds**49a. Does this facility have wetponds?**

- ☐ Yes
- ☒ No

50. Manufactured Stormwater Proprietary Units**50a. Does this facility have proprietary units?**

- ☐ Yes
- ☒ No

51. Point of Outfall Discharge: (check all that apply)

- ☒ Municipal storm sewer system
- ☐ Combined sewer system
- ☐ Surface Water
- ☐ On-site recharge
- ☐ Other (describe)
- ☐ Not Applicable

52. Outfall Reconnaissance Inventory**Were all stormwater outfalls inspected during dry weather for signs of non-stormwater discharge?**

- ☐ Yes
- ☒ No
- ☐ Not Applicable

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Other Site Features

Other Site Features**53. Pavement (Roadways and Parking Lots)**☒ Yes☐ No**53a. Type: (check all that apply)**☐ Concrete☒ Asphalt☐ Gravel☐ Other☐ None**53b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**53c. Year of Last Major Reconstruction/Replacement:**

2011

53d. Expected Remaining Useful Life (Years):

15

53e. Cost to Reconstruct/Replace \$:

(No Response)

53f. Comments:

(No Response)

54. Sidewalks☒ Yes☐ No**54a. Type: (check all that apply)**☒ Concrete☐ Asphalt☐ Paver☐ Other**54b. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**54c. Year of Last Major Reconstruction/Replacement:**

2011

54d. Expected Remaining Useful Life (Years):

15

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Other Site Features

54e. Cost to Reconstruct/Replace \$:

(No Response)

54f. Comments:

(No Response)

55. Playgrounds and Playground Equipment☒ Yes☐ No**55a. Condition:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**55b. Year of Last Major Reconstruction/Replacement:**

2005

55c. Expected Remaining Useful Life (Years):

10

55d. Cost to Reconstruct/Replace \$:

(No Response)

55e. Comments:

(No Response)

56. Athletic Fields and Play Fields☐ Yes☒ No**56f. Does the facility have synthetic turf field(s)**☐ Yes☒ No**56f.1 If Yes, how many synthetic turf fields?**

(No Response)

56f.2 Expected Remaining Useful Life of Synthetic Turf Field(s):

(No Response)

56f.3 Type of synthetic turf field infill:

(No Response)

57. Exterior Bleachers / Stadiums☐ Yes☒ No**58. Related Structures (such as Press Boxes, Dugouts, Climbing Walls, etc.)**☐ Yes☒ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Other Site Features

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Substructure

Substructure**59. Foundation (S)****59a. Type (check all that apply):**

- ☒ Reinforced Concrete
- ☐ Masonry on Concrete Footing
- ☐ Other

59b. Evidence of structural concerns (check all that apply):

- ☐ Structural Cracks
- ☐ Heaving/Jacking
- ☐ Decay/Corrosion
- ☐ Water Penetration
- ☐ Unsupported Ends
- ☐ Other
- ☒ None

59c. Condition:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

59d. Year of Last Major Reconstruction/Replacement:

2015

59e. Expected Remaining Useful Life (Years):

20

59f. Cost to Reconstruct/Replace \$:

(No Response)

59g. Comments:

(No Response)

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Building Envelope

BUILDING ENVELOPE**60. Structural Floors (S)****60a. Type (check all that apply):**

- ☒ Reinforced Concrete Slab on Grade
- ☐ Concrete/Metal Deck/Metal Joists
- ☐ Precast Concrete Structural System
- ☐ Wood Deck on Wood Trusses
- ☐ Wood Deck on Wood Joists
- ☐ Concrete Deck on Wood Structure
- ☐ Other (specify)

60b. Evidence of Structural Concerns with Floor Support System (Beams/Joists/Trusses, etc.) (check all that apply):

- ☐ Structural Cracks
- ☐ Unsupported Ends
- ☐ Rot/Decay/Corrosion
- ☐ Deflection
- ☐ Seriously Damaged/Missing Components
- ☐ Other Problems
- ☒ None

60b.1 Describe Other Problems:

(No Response)

60c. Evidence of Structural Concerns with Structural Floor Deck (check all that apply):

- ☐ Cracks
- ☐ Deflection
- ☐ Rot/Decay/Corrosion
- ☒ None

60d. Overall Condition of Structural Floors:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

60e. Year of Last Major Reconstruction/Replacement:

1919

60f. Expected Remaining Useful Life (Years):

30

60g. Cost to Reconstruct/Replace \$:

(No Response)

60h. Comments:

(No Response)

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Building Envelope

61. Exterior Walls/Columns (S)**61a. Material (check all that apply):**

- ☐ Concrete
- ☒ Masonry
- ☐ Steel
- ☐ Wood
- ☐ Other (specify)

61b. Evidence of Structural Concerns with Support System (columns, base plates, connections, etc.) (check all that apply):

- ☐ Structural Cracks
- ☐ Rot/Decay/Corrosion
- ☐ Other Problems
- ☒ None

61b.1 Describe Other Problems:

(No Response)

61c. Evidence of Concerns with Exterior Cladding (check all that apply):

- ☐ Cracks/Gaps
- ☐ Inadequate Flashing
- ☐ Efflorescence
- ☐ Moisture Penetration
- ☐ Rot/Decay/Corrosion
- ☐ Other Problems
- ☒ None

61c.1 Describe Other Problems:

(No Response)

61d. Overall Condition of Exterior Walls/Columns:

- ☐ Excellent
- ☐ Satisfactory
- ☒ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

61e. Year of Last Major Reconstruction/Replacement:

2011

61f. Expected Remaining Useful Life (Years):

5

61g. Cost to Reconstruct/Replace \$:

100,000.00

61h. Comments:

Minor brick re-pointing and cast stone patching needed at select locations. Interior face of exterior wall at attic is deteriorated, particularly where existing window openings have been boarded up. Investigation/ destructive testing is recommended. Window openings should be infilled (toothed in) with solid masonry. Evidence of moisture/ humidity issues within stairwell. Recommend looking into ventilation/ dehumidification.

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Building Envelope

62. Chimneys (S)

- ☒ Yes
☐ No

62a. Material (check all that apply):

- ☒ Masonry
☐ Concrete
☐ Metal
☐ Wood
☐ Other

62a.1 Specify other:

(No Response)

62b. Overall Condition of Chimneys:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical failure

62c. Year of Last Major Reconstruction/Replacement:

2011

62.d Expected Remaining Useful Life (Years):

30

62e. Cost to Reconstruct/Replace \$:

(No Response)

62f. Comments:

(No Response)

63. Parapets (S)

- ☒ Yes
☐ No

63a. Construction Type (check all that apply):

- ☒ Masonry
☐ Concrete
☐ Metal
☐ Wood
☐ Other (specify)

63a.1 Specify Other:

(No Response)

63b. Overall condition of parapets:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Building Envelope

63c. Year of Last Major Reconstruction/Replacement:

2011

63d. Expected Remaining Useful Life (Years):

30

63e. Cost to Reconstruct/Replace \$:

(No Response)

63f. Comments:

2011 Roofing replacement called for removal and cleaning of spray foam roofing residue from existing clay copying stones. Residue remains and should be cleaned. foam is currently intact, but is deteriorating

64. Exterior Doors**64a. Overall Condition of Exterior Door Units:**

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

64b. Overall condition of exterior door hardware:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

64c. Do any exterior doors have magnetic locking devices?

- ☐ Yes
- ☒ No

64d. Safety/Security features are adequate?

- ☒ Yes
- ☐ No

64e. Year of Last Major Reconstruction/Replacement:

1996

64f. Expected Remaining Useful Life (Years):

10

64g. Cost to Reconstruct/Replace \$:

(No Response)

64h. Comments:

(No Response)

65. Exterior Steps, Stairs, Ramps (S)

- ☒ Yes
- ☐ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Building Envelope

65a. Overall Condition of Exterior Steps, Stairs and Ramps

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

65b. Year of Last Major Reconstruction/Replacement:

2015

65c. Expected Remaining Useful Life (Years):

8

65d. Cost to Reconstruct/Replace \$:

30,000.00

65e. Comments:

Stair patch installed in 2011 is deteriorating. recommend deeper patching methods, or full replacement of stairs. stair on north side of gymnasium re-set/ re-attached to building and painted in 2015. No work performed on south side of gymnasium.

66. Fire Escapes (S)**66a. Does This Facility Have One or More Fire Escapes?**

- ☐ Yes
- ☒ No

67. Windows

- ☒ Yes
- ☐ No

67a. Window Material: (check all that apply)

- ☒ Aluminum
- ☐ Steel
- ☐ Vinyl
- ☐ Solid Wood
- ☐ Wood w/ External Cladding System
- ☐ Other

67b. Overall Condition of Windows:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

67c. All Rescue Windows are Operable:

- ☒ Yes
- ☐ No
- ☐ N/A

67d. Year of Last Major Reconstruction/Replacement:

1996

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Building Envelope

67e. Expected Remaining Useful Life (Years):

5

67f. Cost to Reconstruct/Replace \$:

75,000.00

67g. Comments:

Balances and screens need review and repair/ replacement. Several windows dont stay open. several screenns are damaged or missing.

Roof and Skylights (S)**68. Roof and Skylights (S)**☒ Yes☐ No**68a. Type of roof construction (check all that apply):**

- ☐ Metal deck on metal trusses/joists
- ☐ Wood deck on wood trusses/joists
- ☐ Wood deck on metal trusses/joists
- ☐ Concrete on metal deck on metal trusses/joists
- ☒ Other (describe below)

68a.1 Other roof construction type:

reinforced concrete slab w/ cast in place concrete structure

68b. Type of roofing material (check all that apply):

- ☒ Single-ply membrane
- ☐ Built-up
- ☐ Asphalt shingle
- ☐ Pre-formed metal
- ☐ IRMA
- ☐ Slate
- ☐ Other (describe below)

68b.1 Other roofing material:

(No Response)

68c. Evidence of structural concerns with roof support system (beams/joists/trusses, etc.) (check all that apply):

- ☐ Structural cracks
- ☐ Unsupported ends
- ☐ Rot/Decay/Corrosion
- ☐ Deflection
- ☐ Seriously damaged/missing components
- ☐ Other concerns (describe)
- ☒ None

68c.1 Describe other concerns:

(No Response)

68d. Evidence of structural concerns with roof deck (check all that apply):

- ☐ Cracks
- ☐ Deflection
- ☐ Rot/Decay/Corrosion
- ☒ None

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Building Envelope

68e. Does this facility have skylights?

- ☐ Yes
☒ No

68f. Skylight material (check all that apply):

- ☐ Plastic
☐ Glass
☐ Other
☒ N/A

68g. Overall condition of skylights:

- ☐ Excellent
☐ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

68h. Evidence of concerns with roofing, skylights, flashings, and drains (check all that apply):

- ☐ Failures/Splits/Cracks
☐ Rot/Decay/Corrosion
☐ Inadequate flashing/curbs/pitch pockets
☐ Inadequate or poorly functioning roof drains
☐ Evidence of water penetration/active leaks
☐ Other (specify)
☒ None

68h.1 Specify other concerns:

(No Response)

68i. Overall Condition of Roof and Skylights:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

68j. Year of Last Major Reconstruction/Replacement:

2011

68k. Expected Remaining Useful Life (Years):

25

68l. Cost to Reconstruct/Replace \$:

(No Response)

68m. Comments:

(No Response)

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Interior Spaces

INTERIOR SPACES**69. Interior Bearing Walls and Fire Walls (S)**☒ Yes☐ No**69a. Overall condition of interior bearing walls and fire walls:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-functioning☐ Critical Failure**69b. Year of Last Major Reconstruction/Replacement:**

2015

69c. Expected Remaining Useful Life (Years):

15

69d. Cost to Reconstruct/Replace \$:

(No Response)

69e. Comments:

(No Response)

Other Interior Walls**70. Other Interior Walls**☒ Yes☐ No**70a. Overall condition of other interior walls:**☐ Excellent☐ Satisfactory☒ Unsatisfactory☐ Non-Functioning☐ Critical Failure**70b. Year of Last Major Reconstruction/Replacement:**

2015

70c. Expected Remaining Useful Life (Years):

5

70d. Cost to Reconstruct/Replace \$:

120,000.00

70e. Comments:

Plaster/ paint deterioration in basement, Rooms 008, 022, 121B, 214, 218, 220, 222, and entire attic. Investigation/ destructive testing recommended.

Floor Finishes**71. Carpet**☒ Yes☐ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Interior Spaces

71a. Where located (check all that apply):

- ☒ Instructional Space
- ☒ Common Area

71b. Condition:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

71c. Year of Last Major Reconstruction/Replacement:

2001

71d. Expected Remaining Useful Life (Years):

8

71e. Cost to Reconstruct/Replace \$:

45,000.00

71f. Comments:

(No Response)

72. Resilient Tiles or Sheet Flooring

- ☒ Yes
- ☐ No

72a. Where located (check all that apply):

- ☒ Instructional Space
- ☒ Common Area

72b. Overall condition of resilient tiles or sheet flooring:

- ☐ Excellent
- ☐ Satisfactory
- ☒ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

72c. Year of Last Major Reconstruction/Replacement:

2005

72d. Expected Remaining Useful Life (Years):

1

72e. Cost to Reconstruct/Replace \$:

51,000.00

72f. Comments:

Floors in the Classroom 015 and Faculty Lounge 111 are soft and starting to buckle. Tile buckling in Room 118A near radiator, possible leak.

73. Hard Flooring (concrete; ceramic tile; stone; etc)

- ☒ Yes
- ☐ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Interior Spaces

73a. Where located (check all that apply):

- ☒ Instructional Space
- ☒ Common Area

73b. Overall condition of hard flooring:

- ☐ Excellent
- ☐ Satisfactory
- ☒ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

73c. Year of Last Major Reconstruction/Replacement:

2001

73d. Expected Remaining Useful Life (Years):

15

73e. Cost to Reconstruct/Replace \$:

100,000.00

73f. Comments:

Exposed concrete floors are not level; leaving gaps below doors and not allowing doors to function properly. Recommend grinding and/ or leveling of concrete floor at all occupied spaces and corridors with this type of flooring

.

74. Wood Flooring

- ☒ Yes
- ☐ No

74a. Where located (check all that apply):

- ☒ Instructional Space
- ☒ Common Area

74b. Overall condition of wood flooring:

- ☐ Excellent
- ☐ Satisfactory
- ☒ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

74c. Year of Last Major Reconstruction/Replacement:

1998

74d. Expected Remaining Useful Life (Years):

3

74e. Cost to Reconstruct/Replace \$:

100,000.00

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Interior Spaces

74f. Comments:

Cost is to refinish existing wood flooring in classrooms, however the existing floors may not have enough thickness to be refinished. If it is not possible to refinish the existing wood floors, flooring should be replaced.

Ceilings (H)**75. Ceilings (H)**

- ☒ Yes
☐ No

75a. Overall condition of ceilings:

- ☐ Excellent
☐ Satisfactory
☒ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

75b. Year of Last Major Reconstruction/Replacement:

2005

75c. Expected Remaining Useful Life (Years):

7

75d. Cost to Reconstruct/Replace \$:

131,000.00

75e. Comments:

Localized areas of patching needed. Patch and paint 1000 sf., replace damaged ceiling/ ceiling tiles.

Lockers**76. Lockers**

- ☐ Yes
☒ No

76d. Cost to Reconstruct/Replace \$:

(No Response)

Interior Doors**77. Interior Doors**

- ☒ Yes
☐ No

77a. Overall condition of interior door units:

- ☐ Excellent
☐ Satisfactory
☒ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Interior Spaces

77b. Overall condition of interior door hardware:

- ☐ Excellent
- ☐ Satisfactory
- ☒ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

77c. Year of Last Major Reconstruction/Replacement:

2015

77d. Expected Remaining Useful Life (Years):

5

77e. Cost to Reconstruct/Replace \$:

510,000.00

77f. Comments:

Replace doors, frames, and hardware with compliant fire rated doors, frames, hardware and safety glazing. Replace all original wood doors, frames, and hardware. Replace non-compliant/ non-rated doors, frames, and/or hardware.

Interior Stairs (S)**78. Interior Stairs (S)**

- ☒ Yes
- ☐ No

78a. Overall condition of interior stairs:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

78b. Year of Last Major Reconstruction/Replacement:

1996

78c. Expected Remaining Useful Life (Years):

20

78d. Cost to Reconstruct/Replace \$:

(No Response)

78e. Comments:

Stairs are structurally sound, but configuration, low head height, and wire glass partitions should be reviewed. With current configuration, the majority of doors are not able to be held open with magnetic hold opens. Evidence of moisture issues/ dampness. Recommend review of ventilation/ dehumidification.

Elevator, Lifts and Escalators (H)**79. Elevator, Lift, and Escalators (H)**

- ☒ Yes
- ☐ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Interior Spaces

79a. Overall condition of elevators, lifts, escalators:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

79b. Year of Last Major Reconstruction/Replacement:

2001

79c. Expected Remaining Useful Life (Years):

20

79d. Cost to Reconstruct/Replace \$

(No Response)

79e. Comments:

(No Response)

Interior Electrical Distribution (H)**80. Interior Electrical Distribution (H)**

- ☒ Yes
- ☐ No

80a. Interior electrical supply meets current needs:

- ☒ Yes
- ☐ No

80b. Condition of interior electrical distribution:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

80c. Year of Last Major Reconstruction/Replacement:

2006

80d. Expected Remaining Useful Life (Years):

5

80e. Cost to Reconstruct/Replace \$:

203,000.00

80f. Comments:

Replace panels that were not done during upgrade.

Lighting Fixtures**81. Interior Lighting Fixtures**

- ☒ Yes
- ☐ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Interior Spaces

81a. Condition of interior lighting fixtures:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

81b. Year of Last Major Reconstruction/Replacement:

2000

81c. Expected Remaining Useful Life (Years):

5

81d. Cost to Reconstruct/Replace \$:

105,000.00

81e. Comments:

Replace fixtures that were not upgraded with last renovation

Communication Systems (H)**82. Communication Systems (H)**

- ☒ Yes
- ☐ No

82a. Communication systems are adequate:

- ☒ Yes
- ☐ No

82b. Condition of communication systems:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

82c. Year of Last Major Reconstruction/Replacement:

1990

82d. Expected Remaining Useful Life (Years):

5

82e. Cost to Replace/Reconstruct \$:

119,000.00

82f. Comments:

Upgrade P/A system and speakers

Swimming Pool and Swimming Pool Systems**83. Swimming Pool and Swimming Pool Systems**

- ☐ Yes
- ☒ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Plumbing (Excluding HVAC Systems)

PLUMBING**84. Water Distribution System (H)**☒ Yes☐ No**84a. Types of pipes (check all that apply):**

- ☒ Iron
- ☒ Galvanized
- ☒ Copper
- ☐ Lead
- ☐ PVC
- ☐ Other

84b. Overall condition of water distribution system:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

84c. Year of Last Major Reconstruction/Replacement:

1970

84d. Expected Remaining Useful Life (Years):

5

84e. Cost to Reconstruct/Replace \$:

182,000.00

84f. Comments:

Replace all galvanize piping, replace all old valves

Plumbing Drainage System (H)**85. Plumbing Drainage System (H)**☒ Yes☐ No**85a. Types of pipes (check all that apply):**

- ☒ Iron
- ☐ Galvanized
- ☒ Copper
- ☐ Lead
- ☒ PVC
- ☐ Other

85b. Overall condition of drainage system:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Plumbing (Excluding HVAC Systems)

85c. Year of Last Major Reconstruction/Replacement:

1970

85d. Expected Remaining Useful Life (Years):

5

85e. Cost to Reconstruct/Replace \$:

140,000.00

85f. Comments:

Replace older piping in the building

Hot Water Heaters (H)**86. Hot Water Heaters (H)**☒ Yes☐ No**86a. Type of fuel (check all that apply):**☐ Oil☒ Natural Gas☐ Electricity☐ Propane☐ Other**86b. Overall condition of hot water heaters:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**86c. Year of Last Major Reconstruction/Replacement:**

2000

86d. Expected Remaining Useful Life (Years):

5

86e. Cost to Reconstruct/Replace \$:

15,000.00

86f. Comments:

(No Response)

Plumbing Fixtures**87. Plumbing Fixtures**☒ Yes☐ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Plumbing (Excluding HVAC Systems)

87a. Overall condition of plumbing fixtures (including toilets, urinals, lavatories, etc):

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

87b. Year of Last Major Reconstruction/Replacement:

2000

87c. Expected Remaining Useful Life (Years):

5

87d. Cost to Reconstruct/Replace \$:

42,000.00

87e. Comments:

Replace older fixtures. Replace faucets with self closing type

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

HVAC Systems

HVAC SYSTEMS**88. HVAC Systems Type****88a. Does this building have a central HVAC system?**

- ☐ Yes
☒ No

Heat Generating Systems (H)**88b.1 Other central HVAC system technology:**

(No Response)

89. Heat Generating Systems (H)

- ☒ Yes
☐ No

89a. Heat generation source (check all that apply):

- ☐ Boiler / Hot Water
☒ Boiler / Steam
☐ Furnace / Forced Air
☐ Unit Ventilation
☐ Geothermal
☐ Biomass
☐ Electric
☐ Other (describe below)

89a.1 Other heat generation source:

(No Response)

89b. Overall condition of heat generating systems:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

89c. Year of Last Major Reconstruction/Replacement:

2015

89d. Expected Remaining Useful Life (Years):

15

89e. Cost to Reconstruct/Replace \$:

(No Response)

89f. Comments:

(No Response)

Heating Fuel/Energy Systems (H)**90. Heating Fuel / Energy Systems (H)**

- ☒ Yes
☐ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

HVAC Systems

90a. Overall condition of heating fuel / energy systems:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

90b. Year of Last Major Reconstruction/Replacement:

2015

90c. Expected Remaining Useful Life (Years):

15

90d. Cost to Reconstruct/Replace \$:

(No Response)

90e. Comments:

(No Response)

Cooling/Air Conditioning Generating Systems**91. Cooling / Air-Conditioning Generating Systems**

- ☒ Yes
- ☐ No

91a. Overall condition of cooling/air-conditioning generating systems:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

91b. Year of Last Major Reconstruction/Replacement:

2000

91c. Expected Remaining Useful Life (Years):

11

91d. Cost to Reconstruct/Replace \$:

(No Response)

91e. Comments:

(No Response)

AIR HANDLING AND VENTILATION EQUIPMENT**92. Air Handling and Ventilation Equipment: Supply Units, Exhaust Units, Relief/Return Units, etc. (H)**

- ☒ Yes
- ☐ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

HVAC Systems

92a. Overall condition of air handling and ventilation systems:

- ☐ Excellent
- ☐ Satisfactory
- ☒ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

92b. Year of Last Major Reconstruction/Replacement:

1922

92c. Expected Remaining Useful Life (Years):

3

92d. Cost to Reconstruct/Replace \$:

1,190,500.00

92e. Comments:

Add HVAC System to the Building

Piped Heating and Cooling Distribution Systems**93. Piped Heating and Cooling Distribution Systems: Piping, Pumps, Radiators, Convectorss, Traps, Insulation, etc. (H)**

- ☒ Yes
- ☐ No

93a. Overall condition of piped heating and cooling distribution systems:

- ☐ Excellent
- ☒ Satisfactory
- ☐ Unsatisfactory
- ☐ Non-Functioning
- ☐ Critical Failure

93b. Year of Last Major Reconstruction/Replacement:

1970

93c. Expected Remaining Useful Life (Years):

5

93d. Cost to Reconstruct/Replace \$:

483,000.00

93e. Comments:

Provide new heating hot water piping system to new equipment

Ducted Heating and Cooling Distrbution Systems**94. Ducted Heating and Cooling Distribution Systems: Ductwork, Control Dampers, Fire/Smoke Dampers, VAVs, Insulation, etc. (H)**

- ☐ Yes
- ☒ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

HVAC Systems

HVAC Control Systems**95. HVAC Control Systems (H)**☒ Yes☐ No**95a. Overall condition of control systems:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**95b. Year of Last Major Reconstruction/Replacement:**

1970

95c. Expected Remaining Useful Life (Years):

3

95d. Cost to Reconstruct/Replace \$:

525,000.00

95e. Comments:

Upgrade to DDC Controls

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Fire Safety Systems

Fire Safety Systems**96. Fire Alarm Systems (H)**☒ Yes☐ No**96a. Overall condition of fire alarm system:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**96b. Year of Last Major Reconstruction/Replacement:**

2000

96c. Expected Remaining Useful Life (Years):

5

96d. Cost to Reconstruct/Replace \$:

135,000.00

96e. Comments:

Replace current system with addressable system

Smoke Detection System (H)**97. Smoke Detection Systems (H)**☒ Yes☐ No**97a. Overall condition of smoke detection systems:**☐ Excellent☒ Satisfactory☐ Unsatisfactory☐ Non-Functioning☐ Critical Failure**97b. Year of Last Major Reconstruction/Replacement:**

2000

97c. Expected Remaining Useful Life (Years):

5

97d. Cost to Reconstruct/Replace \$:

(No Response)

97e. Comments:

Cost carried in item #96

Fire Suppression Systems

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Fire Safety Systems

98. Fire Suppression Systems: Sprinklers, Standpipes, Kitchen Hoods, etc. (H)

- ☒ Yes
☐ No

98a. Overall condition of fire suppression systems:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

98b. Year of Last Major Reconstruction/Replacement:

1970

98c. Expected Remaining Useful Life (Years):

11

98d. Cost to Reconstruct/Replace \$:

(No Response)

98e. Comments:

(No Response)

Emergency/Exit Lighting Systems**99. Emergency / Exit Lighting Systems (H)**

- ☒ Yes
☐ No

99a. Overall condition of emergency / exit lighting systems:

- ☐ Excellent
☒ Satisfactory
☐ Unsatisfactory
☐ Non-Functioning
☐ Critical Failure

99b. Year of Last Major Reconstruction/Replacement:

2015

99c. Expected Remaining Useful Life (Years):

15

99d. Cost to Reconstruct/Replace \$:

(No Response)

99e. Comments;

(No Response)

Emergency/Standby Power Systems**100. Emergency or Standby Power System (H)**

- ☐ Yes
☒ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Accessibility

ACCESSIBILITY**101. Exterior Accessible Route (H)**

People with disabilities should be able to arrive on site, approach the building, and enter as freely as everyone else. At least one route of travel should be safe and accessible for everyone, including people with disabilities. This route must include handicapped parking, curb cuts, ramps, and automatic door operators as necessary to enter the building.

Is there an accessible exterior route as specified above?

- ☒ Yes
☐ No

102. Interior Accessible Route, Access to Goods and Services, and Restroom Facilities (H)

The layout of the building should allow people with disabilities to obtain materials or services and use the facilities without assistance. This should include access to general purpose and specialized classrooms, public assembly spaces (such as libraries, gymnasiums, auditoriums), nurse's office, main office, and restroom facilities. Services include drinking fountains, telephones, and other amenities.

Is there an accessible interior route as specified above?

- ☒ Yes
☐ No

103. Additional Information on Accessibility

If the building lacks accessible interior or exterior routes:

103a. Cost of improvements needed to provide accessible exterior and interior routes as specified above \$:

(No Response)

103b. Comments:

(No Response)

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Environment/Comfort/Health

ENVIRONMENT/COMFORT/HEALTH**104. General Appearance****104a. Overall Rating:**

- ☒ Good
- ☐ Fair
- ☐ Poor

104b. Comments:

(No Response)

105. Cleanliness**105a. Overall Rating:**

- ☒ Good
- ☐ Fair
- ☐ Poor

105b. Comments:

(No Response)

106. Are there walk off mats; grills in the entryway?

- ☒ Yes
- ☐ No

106a. If yes: at least 6 feet long?

- ☒ Yes
- ☐ No

107. Is there noise in classrooms from HVAC units, traffic, etc. that may impact education?

- ☐ Yes
- ☒ No

108. Lighting Quality:**108a. Types of lighting in general purpose classrooms (check all that apply):**

- ☒ Daylight
- ☒ Fluorescent-not full spectrum
- ☐ Fluorescent full spectrum
- ☐ Incandescent
- ☐ Other (describe)

108b. Are there blinds in the classroom to prevent glare?

- ☒ Yes
- ☐ No

108c. Overall Rating:

- ☒ Good
- ☐ Fair
- ☐ Poor

108d. Comments:

(No Response)

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Environment/Comfort/Health

109. Evidence of Vermin

109a. Is there evidence of active infestations of...(check all that apply)?

- ☐ Rodents
- ☐ Wood-boring or Wood-eating Insects
- ☐ Cockroaches
- ☐ Other Vermin
- ☒ None

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Indoor Air Quality

Indoor Air Quality**110. Mold****110a. Is there visible mold or moldy odors?**

- ☐ Yes
☒ No

110c. Are any surfaces constructed of any of the following materials?

- ☒ Paper-faced or gypsum products
☒ Cellulose products (typically ceiling tiles)

110d. Estimated cost of necessary improvements \$:

(No Response)

110d. Comments:

(No Response)

111. Humidity/Moisture**111a. Overall rating of humidity/moisture condition in building:**

- ☐ Good
☒ Fair
☐ Poor

111b. Are any of the following found in/or around classroom areas (check all that apply)?

- ☐ Active leaks in roof
☐ Active leaks in plumbing
☐ Moisture condensation
☐ Visible stains or water damage
☒ None

111c. Are any of the following found in/or around other areas (check all that apply)?

- ☐ Active leaks in roof
☐ Active leaks in plumbing
☒ Moisture condensation
☒ Visible stains or water damage
☐ None

112. Ventilation: fresh air intake locations, air filters, etc.**112a. Are fresh air intakes near the bus loading, truck delivery, or garbage storage/disposal areas?**

- ☐ Yes
☒ No

112b. Is there accumulated dirt, dust or debris around fresh air intakes?

- ☐ Yes
☒ No

112c. Are fresh air intakes free of blockage?

- ☐ Yes
☒ No

112d. Is accumulated dirt, dust or debris in ductwork?

- ☐ Yes
☒ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Indoor Air Quality

112e. Are dampers functioning as designed?

- ☐ Yes
☒ No

112f. Condition of air filters:

- ☐ Good
☐ Fair
☒ Poor

112g. Outside air is adequate for occupant load:

- ☐ Yes
☒ No

112h. Rating of ventilation/indoor air quality:

- ☐ Good
☐ Fair
☒ Poor

112i. Comments:

(No Response)

113. Indoor Air Quality (IAQ) Plan**113a. Does the school district use EPA's Tools for Schools program?**

- ☐ Yes
☒ No

113b. If No, is some other IAQ management plan used?

- ☐ Yes
☒ No

113c. Has the District assigned IAQ responsibilities to a designated individual?

- ☒ Yes
☐ No

113c.1 If Yes, what is their job title?

Supervisor Building and Grounds

114. Does the school practice IPM?

- ☒ Yes
☐ No

114a. Is vegetation kept one foot away from the building?

- ☒ Yes
☐ No

114b. Are crevices and holes in walls, floors and pavement sealed or eliminated?

- ☒ Yes
☐ No

114c. Is there a certified pesticide applicator on staff?

- ☐ Yes
☒ No

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

Indoor Air Quality

114d. Are pesticides used in the building?

- ☒ Yes
☐ No

114d.1 If Yes, how are they typically applied?

- ☒ Spot treatment
☐ Area wide treatments

114e. Are pesticides used on the grounds?

- ☐ Yes
☒ No

114e.1 If Yes, was an emergency exemption granted by the Board of Education?

- ☐ Yes
☐ No

115. Does the school have a passive radon mitigation system installed (was built with radon resistant features)?

- ☐ Yes
☒ No

115a. Has the facility been tested for the presence of radon?

- ☐ Yes
☒ No

115b. Were any of the results of the test greater than or equal to 4 picocuries per liter (pCi/L)?

- ☐ Yes
☐ No

115c. If Yes, did the school take steps to mitigate the elevated radon levels?

- ☐ Yes, active mitigation system installed
☐ Yes, passive mitigation system made active
☐ Yes, ventilation controls (HVAC) adjusted
☐ Yes, other (describe)
☐ No action taken

115c.1 Describe other actions taken to mitigate elevated radon levels:

(No Response)

2015 Building Condition Survey Instrument - 2015 Building Conditions Survey - PLEASANT VALLEY

American Red Cross

American Red Cross Shelter

116. American Red Cross Shelter

☐ Yes

☒ No