

	School District:	Schenectady City School				
	School Name:	Paige				
Sample #	Location	Source	Sample Date	Results (ppb)	Initial Status*	Remediation P
PAI-001	Hallway outside Room 6	water fountain		< 1.0	Passed	
PAI-002	Room 1	sink with water fountain		< 1.0	Passed	
PAI-003	Room 2	sink with water fountain		< 1.0	Passed	
PAI-004	Room 3	sink with water fountain		< 1.0	Passed	
PAI-005	Room 4	sink with water fountain		1.2	Passed	
PAI-006	Room 5A	sink with water fountain		< 1.0	Passed	
PAI-007	Room 7	sink with water fountain		< 1.0	Passed	
PAI-008	Room 8	sink with water fountain		2	Passed	
PAI-009	Room 9	sink with water fountain		1.2	Passed	
PAI-010	Room 10	Room 10 sink with water fountain		1.4	Passed	
PAI-011	Room 11	Room 11 sink with water fountain		9.3	Passed	
PAI-012	Room 12	Room 12 sink with water fountain		7.2	Passed	
PAI-013	Room 13	Room 13 sink with water fountain		1.8	Passed	
PAI-014	Room 14	Room 14 sink with water fountain		4.5	Passed	
PAI-015	Room 15	Room 15 sink with water fountain		3.5	Passed	
PAI-016	Nurses Office	sink		2.2	Passed	
PAI-017	Nurses Office	sink in bathroom		5.2	Passed	
PAI-018	Room 16	sink with water fountain		7.1	Passed	
PAI-019	Room 17	sink with water fountain		9.4	Passed	
PAI-020	Room 18	sink with water fountain		14	Passed	
PAI-021	Room 19	sink with water fountain		7.1	Passed	
PAI-022	Room 20	sink with water fountain		12	Passed	
PAI-023	Room 21	sink with water fountain		9.6	Passed	
PAI-024	Hallway outside Main Off	water fountain		5	Passed	
PAI-025	Hallway next to Mechanic	water fountain		< 1.0	Passed	
PAI-026	Hallway next to Custodia	water fountain		< 1.0	Passed	
PAI-028	Kitchen Food Prep	sink		< 1.0	Passed	

