

	School District:	Schenectady City School									
	School Name:	Pleasant Valley									
Sample #	Location	Source	Sample Date	Results (ppb)	Initial Status*	Remediation	Remediation	Resample Date	Resample	Status*	2020 Sample
PV-001	3rd Floor outside Room 216	Water Fountain		9	Passed						
PV-002	3rd Floor outside Room 206	Water Fountain		1.3	Passed						
PV-003	2nd Floor outside Room 106	Water Fountain		1.4	Passed						
PV-004	2nd Floor Faculty Room	Sink		< 1.0	Passed						
PV-005	2nd Floor outside Room 116	Water Fountain		5.1	Passed						
PV-006	1st Floor Kitchen Food Prep	Sink		< 1.0	Passed						
PV-007	1st Floor Room 16	Sink		2.6	Passed						
PV-009	1st Floor Room 14	Sink		< 1.0	Passed						
PV-010	1st Floor Room 14	Water Fountain		3.3	Passed						
PV-011	1st Floor across from Main Office	Water Fountain		250	Failed			5/19/2018	1.6		
PV-012	1st Floor Room 10	Sink		1.2	Passed						
PV-013	1st Floor Nurses Office	Sink		< 1.0	Passed						
PV-014	1st Floor Nurses Office Bathroom	Sink		< 1.0	Passed						
PV-015	1st Floor Room 1	Sink		< 1.0	Passed						
PV-016	1st Floor Room 002	Water Fountain		< 1.0	Passed						

