

	School District:	Schenectady City School										
	School Name:	Van Corlaer										
Sample #	Location	Source	Sample Date	Results (ppb)	Initial Status*	Remediati	Remediati	Resample	Resample	Status*	2020 Samp	Results (pp
VC-001	3rd Floor Hallway	water fountain		4.5	Passed							
VC-002	2nd Floor Nurses Office	sink #1		1	Passed							
VC-003	2nd Floor Nurses Office	sink #2		2.3	Passed							
VC-004	2nd Floor outside Room 20	water fountain		1.1	Passed							
VC-005	2nd Floor Room 209	water fountain		1.6	Passed							
VC-006	2nd Floor outside Room 20	water fountain		< 1.0	Passed							
VC-007	1st Floor outside Room 10	water fountain		< 1.0	Passed							
VC-008	1st Floor Main Office	sink		7.7	Passed							
VC-009	1st Floor outside Room 10	water fountain		1.3	Passed							
VC-010	Basement Faculty Room	sink		< 1.0	Passed							
VC-011	Basement Cafeteria	water fountain		< 1.0	Passed							
VC-012	Basement Kitchen Food Pre	sink		< 1.0	Passed							
VC-013	Basement Room B15A	sink		9.1	Passed							

