

	School District:	Schenectady City School							
	School Name:	Woodlawn							
Sample #	Location	Source	Sample Date	Results (ppb)	Initial Status*	Remediation #	Remediation D	Resample Dat	Resample Res
WDL-001	2nd Floor at top of center stairs #1	water fountain		1.4	Passed				
WDL-002	2nd Floor at top of center stairs #2	water fountain		1.4	Passed				
WDL-003	2nd Floor Room 30	sink		4.2	Passed				
WDL-004	2nd Floor Room 26	sink		9.6	Passed				
WDL-005	1st Floor Library near door	sink		3.3	Passed				
WDL-006	1st Floor center stairs #1	water fountain		2.6	Passed				
WDL-007	1st Floor center stairs #2	water fountain		1.2	Passed				
WDL-008	1st Floor Room 4	sink		1.7	Passed				
WDL-009	1st Floor Nurses Office	sink		1.8	Passed				
WDL-010	1st Floor Nurses Office	bathroom sink		< 1.0	Passed				
WDL-011	1st Floor Main Office	water fountain		< 1.0	Passed				
WDL-012	1st Floor Faculty Room	sink #1		4.7	Passed				
WDL-013	1st Floor Faculty Room	sink #2		1.4	Passed				
WDL-014	1st Floor Faculty Room	sink #3		2.1	Passed				
WDL-015	1st Floor Cafeteria	water fountain		< 1.0	Passed				
WDL-016	1st Floor Room 14	sink		8.8	Passed				
WDL-017	1st Floor Hallway across from Room	water fountain		1.1	Passed				
WDL-018	1st Floor Room 16	sink in closet		4.1	Passed				
WDL-019	1st Floor Room 18	sink		2.6	Passed				
WDL-020	1st Floor OT/PT Room	water fountain		2.5	Passed				
WDL-021	1st Floor Room 19A	sink with water fountain		2.8	Passed				
WDL-022	1st Floor Art Room closet	sink with water fountain		2.8	Passed				
WDL-023	1st Floor Kitchen Food Prep	sink		< 1.0	Passed				

