

	<b>School District:</b>	Schenectady City School									
	<b>School Name:</b>	Yates									
Sample #	Location	Source	Sample Date	Results (ppb)	Initial Status*	Remediati	Remediati	Resample Date	Resample	Status*	2020 Samp
YAT-001	3rd Floor Hallway outside elevator	water fountain		< 1.0	Passed						
YAT-002	3rd Floor Storage Room	sink		18	Failed	removed					
YAT-003	2nd Floor Faculty Room	sink		7.1	Passed						
YAT-004	2nd Floor Hallway outside Room 205	water fountain		3.8	Passed						
YAT-005	2nd Floor Hallway outside Room 206	water fountain		1.1	Passed						
YAT-006	1st Floor Room 107	closet sink		7.2	Passed						
YAT-007	1st Floor Hallway outside Room 106	water fountain		3.6	Passed						
YAT-008	1st Floor Hallway across from Main Office			3.8	Passed						
YAT-009	1st Floor Room 100	sink		8.9	Passed						
YAT-010	1st Floor Hallway outside Room 105	water fountain		< 1.0	Passed						
YAT-011	1st Floor Room 115	sink with water fountain (new wing)		12	Passed						
YAT-012	1st Floor Room 114	sink with water fountain (new wing)		25	Failed			5/19/2018	3.3	Passed	
YAT-013	1st Floor Room 113	sink with water fountain (new wing)		7	Passed						
YAT-014	1st Floor Room 112	sink with water fountain (new wing)		4.5	Passed						
YAT-015	1st Floor Room 111	sink with water fountain (new wing)		5.6	Passed						
YAT-016	1st Floor Room 110	sink with water fountain (new wing)		8.2	Passed						
YAT-017	1st Floor Room 109	sink with water fountain (new wing)		16	Failed			5/19/2018	40		
YAT-018	Basement Gym	water fountain		No sample	Passed						
YAT-019	Basement Hallway outside Gym	water fountain		4.6	Passed						
YAT-020	Basement Hallway outside Custodial Offi	water fountain		11	Passed						
YAT-021	Basement Kitchen Food Prep	sink		4.6	Passed						
YAT-022	Basement Art Room	sink		8.9	Passed						
YAT-023	Basement Custodial Room	sink		40	Failed				49		

