

	<b>School District:</b>	Schenectady City School								
	<b>School Name:</b>	Oneida Middle								
<b>Sample #</b>	<b>Location</b>	<b>Source</b>	<b>Sample Date</b>	<b>Results (ppb)</b>	<b>Initial Status*</b>	<b>Remediated</b>	<b>Remediated</b>	<b>Resample</b>	<b>Resample</b>	<b>Status*</b>
OMS-001	2nd Floor Room 213	sink #1		14.2	Passed					
OMS-002	2nd Floor Room 213	sink #2		14.6	Passed					
OMS-003	2nd Floor Hallway outside Bathroom T215	water fountain		None Detected	Passed					
OMS-004	2nd Floor Room 227	sink #1		0.17	Passed					
OMS-005	2nd Floor Room 227	sink #2		0.11	Passed					
OMS-006	2nd Floor Room 229	sink #1		0.3	Passed					
OMS-007	2nd Floor Room 229	sink #2		0.33	Passed					
OMS-008	2nd Floor Room 231	sink		0.25	Passed					
OMS-009	2nd Floor Room 239	sink #1		7	Passed					
OMS-010	2nd Floor Room 239	sink #2		4.4	Passed					
OMS-011	2nd Floor Room 241	sink #1		8.9	Passed					
OMS-012	2nd Floor Room 241	sink #2		9.3	Passed					
OMS-013	2nd Floor Hallway outside Bathroom T249	water fountain		None Detected	Passed					
OMS-014	2nd Floor Room 251	sink #1		8.8	Passed					
OMS-015	2nd Floor Room 251	sink #2		5.6	Passed					
OMS-016	2nd Floor Room 251	sink #3		11.8	Passed					
OMS-017	2nd Floor Room 251	sink #4		6.6	Passed					
OMS-018	2nd Floor Room 251	sink #5		No Sample	Passed					
OMS-019	2nd Floor Room 251	sink #6		No Sample	Passed					
OMS-020	2nd Floor Hallway outside Room 258	water fountain		No Sample	Passed					
OMS-021	1st Floor Room 113	sink #1		12	Passed					
OMS-022	1st Floor Room 113	sink #2		7.1	Passed					
OMS-023	T115 1st Floor Hallway outside Bathroom	water fountain		None Detected	Passed					
OMS-024	1st Floor Hallway outside Bathroom T141	water fountain		None Detected	Passed					
OMS-025	1st Floor Room 143	sink #1		9.5	Passed					
OMS-026	1st Floor Room 143	sink #2		9.8	Passed					
OMS-027	1st Floor Room 143	sink #3		6	Passed					
OMS-028	1st Floor Room 143	sink #4		9.9	Passed					
OMS-029	1st Floor Hallway outside Room 104	water fountain		None Detected	Passed					
OMS-030	Ground Floor Room G09	sink #1		7.7	Passed					
OMS-031	Ground Floor Room G09	sink #2		5.9	Passed					
OMS-032	Ground Floor Room G13	sink #1		7.9	Passed					

OMS-033	Ground Floor Room G13	sink #2		7.4	Passed					
OMS-034	Ground Floor Hallway outside Room G15	water fountain		None Detected	Passed					
OMS-035	Ground Floor Room G19	sink		0.82	Passed					
OMS-036	Ground Floor Room G20	sink #1		6	Passed					
OMS-037	Ground Floor Room G20	sink #2		4.2	Passed					
OMS-038	Ground Floor Room G21	sink		0.54	Passed					
OMS-039	Ground Floor Room G23	sink		0.36	Passed					
OMS-040	Ground Floor Room G26	prep sink		No Sample	Passed					
OMS-040A				3.9	Passed					
OMS-040B				1.8	Passed					
OMS-040C				2.8	Passed					
OMS-041	Ground Floor Hallway outside Room G26 #1	water fountain		None Detected	Passed					
OMS-042	Ground Floor Hallway outside Room G26 #2	water fountain		None Detected	Passed					
OMS-043	Ground Floor Hallway outside Room G29	water fountain		None Detected	Passed					
OMS-044	Ground Floor Room G31	sink #1		5.8	Passed					
OMS-045	Ground Floor Room G31	sink #2		7.9	Passed					
OMS-046	Ground Floor Room G35	sink #1		4.8	Passed					
OMS-047	Ground Floor Room G35	sink #2		7.5	Passed					
OMS-048	Ground Floor Hallway outside Room G37	water fountain		None Detected	Passed					
OMS-049	Ground Floor Nurses Office	sink #1		0.94	Passed					
OMS-050	Ground Floor Nurses Office	sink #2		0.31	Passed					
OMS-051	Ground Floor Nurses Office	sink #3		0.43	Passed					
OMS-052	Ground Floor Nurses Office	sink #4		1.1	Passed					
OMS-053	Basement Girls Locker Room	sink #1		0.37	Passed					
OMS-054	Basement Girls Locker Room	sink #2		0.8	Passed					
OMS-055	Basement Hallway outside Room B11 #1	water fountain		None Detected	Passed					
OMS-056	Basement Hallway outside Room B11 #2	water fountain		None Detected	Passed					
OMS-057	Basement Room B12	sink		0.74	Passed					
OMS-058	Basement Boys Locker Room	sink #1		0.53	Passed					
OMS-059	Basement Boys Locker Room	sink #2		0.79	Passed					
OMS-060	Basement Room B15	sink		0.29	Passed					
OMS-061	Basement Room B17	sink		5.4	Passed					

