

	School District:	Schenectady City School									
	School Name:	Steinmetz									
Sample #	Location	Source	Sample Date	Results (ppb)	Initial Status*	Remediation	Remediation	Resample Date	Resample Results	Status*	2020 Sample
SCLA-001	3rd Floor Hallway outside Room B303	water fountain		1.5	Passed						
SCLA-002	3rd Floor Room B303	sink #1		483	Failed			9/13/2018	11.5		
SCLA-003	3rd Floor Room B303	sink #2		No Sample	Passed			9/13/2018	7.1		
SCLA-004	3rd Floor Room B303	sink #3		67.6	Failed			9/13/2018	8.2		
SCLA-005	3rd Floor Room B303	sink #4		12.5	Passed			9/13/2018	10.3		
SCLA-006	3rd Floor Room B302	sink #1		No Sample	Passed						
SCLA-007	3rd Floor Room B302	sink #2		12.5	Passed						
SCLA-008	3rd Floor Room B302	sink #3		No Sample	Passed						
SCLA-009	3rd Floor Room B302	sink #4		No Sample	Passed						
SCLA-010	3rd Floor Room B301	sink #1		16.1	Failed			9/13/2018	1.7		
SCLA-011	3rd Floor Room B301	sink #2		3.6	Passed						
SCLA-012	3rd Floor Room B301	sink #3		3.7	Passed						
SCLA-013	3rd Floor Room B301	sink #4		35.6	Failed			9/13/2018	1.2		
SCLA-014	3rd Floor Room B301 closet	sink #1		630	Failed			9/13/2018	2.9		
SCLA-015	3rd Floor Room B301 closet	sink #2		94	Failed			9/13/2018	2		
SCLA-016	3rd Floor Room B306	sink #1		279	Failed			9/13/2018	1.8		
SCLA-017	3rd Floor Room B306	sink #2		No Sample	Passed			9/13/2018	1.9		
SCLA-018	3rd Floor Room B306	sink #3		14.3	Passed			9/13/2018	ND		
SCLA-019	3rd Floor Room B306	sink #4		22.1	Failed			9/13/2018	ND		
SCLA-020	3rd Floor Room B306	sink #5		95.2	Failed			9/13/2018	ND		
SCLA-021	2nd Floor Hallway outside Room B210	water fountain		9.3	Passed						
SCLA-022	2nd Floor Hallway outside Room B202	water fountain		3.4	Passed						
SCLA-023	1st Floor Hallway outside Room B102	water fountain		1.4	Passed						
SCLA-024	1st Floor Hallway outside Room B110	water fountain		No Sample	Passed						
SCLA-025	Basement Room B10	sink		21	Failed						
SCLA-026	2nd Floor Annex Room A204	sink #1		327	Failed			9/13/2018	1.3		
SCLA-027	2nd Floor Annex Room A204	sink #2		800	Failed			9/13/2018	ND		
SCLA-028	2nd Floor Annex Room A205	Coffee Maker		0.83	Passed						
SCLA-029	2nd Floor Annex Room A205	Ice Maker		1.7	Passed						
SCLA-030	2nd Floor Annex Room A205	sink		10.7	Passed						
SCLA-031	2nd Floor Annex Room A206	sink		67.1	Failed			9/13/2018	ND		

SCLA-032	2nd Floor Annex Room A206	prep sink		1.1	Passed					
SCLA-033	2nd Floor Annex Library Office	sink		151	Failed		9/13/2018	ND		
SCLA-034	2nd Floor Hallway Annex	water fountain outside Library		3.8	Passed					
SCLA-035	2nd Floor Annex Room A201	sink		No Sample	Passed					
SCLA-036	2nd Floor Annex Room A203	sink #1		4.7	Passed					
SCLA-037	2nd Floor Annex Room A203	sink #2		4.3	Passed					
SCLA-038	2nd Floor Annex Room A202	sink #1		No Sample	Passed					
SCLA-039	2nd Floor Annex Room A202	sink #2		No Sample	Passed					
SCLA-040	1st Floor Annex Choral Room 2	sink		65.2	Failed		9/13/2018	26.3		
SCLA-041	1st Floor Annex Choral Room 1	sink		5.2	Passed					
SCLA-042	1st Floor Hallway Annex outside Girls Lo	water fountain		4.8	Passed					
SCLA-043	1st Floor Annex Main Office	sink		3	Passed					
SCLA-044	1st Floor Annex Cafeteria near Boys Bath	water fountain		3.7	Passed					
SCLA-045	1st Floor Annex Kitchen	sink		6.9	Passed					
SCLA-046	1st Floor Annex Nurses Office	sink #1		7.2	Passed					
SCLA-047	1st Floor Annex Nurses Office	sink #2		3.9	Passed					
SCLA-048	1st Floor Annex Nurses Office	sink #3		5.1	Passed					
SCLA-049	1st Floor Annex Nurses Office	sink #4		7.2	Passed					

