

	School District:	Schenectady City School								
	School Name:	Lincoln								
Sample #	Location	Source	Sample Date	Results (ppb)	Initial Status	Remediation	Remediation	Resample Date	Resample	Status*
LIN-001	3rd Floor	Water Fountain outside Boys Bathroom		< 1.0	Passed					
LIN-002	3rd Floor Room 38	sink		6.8	Passed					
LIN-003	3rd Floor	Water Fountain outside Room 31		2.9	Passed					
LIN-004	3rd Floor Room 31	sink		< 1.0	Passed					
LIN-005	2nd Floor	Water Fountain outside Room 24		< 1.0	Passed					
LIN-006	2nd Floor Room 20A	sink		28	Failed	Removed		5/19/2018	117	
LIN-007	2nd Floor	Water Fountain outside Boys Bathroom		< 1.0	Passed					
LIN-008	1st Floor	Water Fountain outside Main Office		< 1.0	Passed					
LIN-009	1st Floor Room 9	sink with water fountain		1.8	Passed					
LIN-010	1st Floor	Water Fountain across from Room 4		< 1.0	Passed					
LIN-011	1st Floor Room 1	sink with water fountain		< 1.0	Passed					
LIN-012	1st Floor Nurses Office	sink		2.1	Passed					
LIN-013	Basement Room B2	sink		5.7	Passed					
LIN-014	Basement Kitchen food pre	sink		1.1	Passed					
LIN-015	Basement	Water Fountain outside Cafeteria		< 1.0	Passed					
LIN-016	Basement Room B3	sink		2.2	Passed					

