

<b>School District:</b>	Schenectady City School
<b>School Name:</b>	Central Park Middle School

Sample #	Location	Source	Sample Date	Results (ppb)	Initial Status*	Remediation Plans	Remediation Date	Resample Date
CPMS-001	2nd fl Annex Hall. By room N8	Water fountain		NO SAMPLE				
CPMS-002	Room 210	Sink		87.7				
CPMS-003	Room 210	Sink		46.5				
CPMS-004	Room 210	Sink		NO SAMPLE				
CPMS-005	Room 210	Sink		NO SAMPLE				
CPMS-006	Room 210	Sink		NO SAMPLE				
CPMS-007	Room 210	Sink		NO SAMPLE				
CPMS-008	Room 210	Sink		NO SAMPLE				
CPMS-009	2nd Fl Hall.	Water fountain		1.5	Passed			
CPMS-010A	Room 211	Sink		3.4	Passed			
CPMS-011	2nd Fl Hall. By Girls Bathroom	Water fountain		NO SAMPLE				
CPMS-012A	1st Floor Nurses Office	Sink		2.2	Passed			
CPMS-013	1st Floor Hallway	Water fountain		NO SAMPLE				
CPMS-014	1st Floor Hallway	Water fountain		0.93	Passed			
CPMS-015	1st Floor Hallway	Water fountain		14.6	Passed			
CPMS-016	Room 110	Sink 1		2.4	Passed			
CPMS-017	Room 110	Sink 2		7	Passed			
CPMS-018	1st Floor Annex Hallway	Water fountain #1 across Main Gym		8.7	Passed			
CPMS-019	1st Floor Annex Hallway	Water fountain #2 across Main Gym		1.7	Passed			
CPMS-020	1st Floor Annex Boys Locker Room	Sink 1		11	Passed			
CPMS-021	1st Floor Annex Boys Locker Room	Sink 2		6.8	Passed			
CPMS-022	1st Floor Annex Boys Locker Room	Sink 3		6.4	Passed			
CPMS-023	1st Floor Annex Boys Locker Room	Sink 4		5.8	Passed			
CPMS-024	Ground Floor Hallway	Water fountain across from Room 8		2.3	Passed			
CPMS-025	Ground Floor room 10	Sink		9.9	Passed			
CPMS-026	Ground Floor Annex	Water fountain outside Room N3		0.72	Passed			
CPMS-027	Ground Floor kitchen food prep	Sink		8.6	Passed			
CPMS-028	Ground Floor kitchen	Sink		3.6	Passed			
CPMS-031	Ground Floor Custodial Room	Sink		0.4	Passed			
CPMS-010B				5	Passed			
CPMS-012B				0.76	Passed			

--	--	--	--	--	--	--	--	--

